

Oklahoma City Transload Terminal Yard Rules



1. All visitors must check in at the office before entering yard.
2. Drivers need to pull onto scale and call the number on signage to check-in.
3. Yard speed limit is 10 MPH.
4. Absolutely no smoking on premises.
5. PPE required beyond the scale:
 - Hard hat
 - High-visibility vest or shirt
 - Safety glasses
 - Steel-toe boots
 - Flame-resistant clothing (for liquid products only)
6. Follow operator's instructions while loading. Do not move truck until operator clears you.
7. Hatch open or closing must be done in the staging area. Safe rack is available.
8. Cell phone use is prohibited while in the yard. Photos or video are not allowed while on Watco property.

Be courteous to all Watco team members.